


# Jordan Transformer Project Examples

## Remanufacture with Complete Core Steel Replacement

20 MVA FOA @ 75° 115 – 24.94Y x 13.2Y x 4.16Y/2.4 Westinghouse Mobile



**Damage to Lid from Failure Allowing  
Exposure to Water**



**Core and Coil Assembly with  
Broken Lead Structure**



**Failed Primary Aluminum Winding**



**Rusted Bottom of Core Steel and Bottom Frame from Water Damage**




Jordan Transformer, LLC

## Jordan Transformer Project Examples

**Post Remanufacture with Complete Core Steel Replacement**


20 MVA FOA @ 75° 115 – 24.94Y x 13.2Y x 4.16Y/2.4 Westinghouse Mobile



**New copper windings with Nomex Insulation**



**All New Core Steel**



**New leads & lead structure**



**New bushings, gauges, arresters, rebuilt pumps, rebuilt switches**

