



Reinhausen LTC Retrofit and Addition of Oil Ducts to Core 24/32/40 MVA 140 – 13.8Y Moloney with LTC



Overhead view of top yolk of core



Overheated Sheets of Center Leg Top Yolk



Signs of core overheating after yolk removal

 Jordan Transformer, LLC **Jordan Transformer Project Examples**

Reinhausen LTC Retrofit and Addition of Oil Ducts to Core



24/32/40 MVA 140 – 13.8Y with Reinhausen RMV-II LTC



New Reinhausen RMV-II Load Tap Changer



Installation of 1/4" Oil Ducts



New Series and PA Windings