


# Jordan Transformer Project Examples

## Fire Damage-(Before)

24/32/40 MVA 138 – 13.8Y ASEA with LTC





Jordan  
Transformer, LLC


# Jordan Transformer Project Examples

Fire Damage Repair & Reconditioning – (After) No Rewinding Needed

24/32/40 MVA 138 – 13.8Y ASEA with LTC



**Overhead view of core & coil assembly before untanking**



**Transformer tested as good and core & coils were able to be reused.**  
**Transformer tank was sandblasted and painted.**  
**New bushings, gauges, fans, wiring and conduit.**  
**New LTC and controls.**  
**Back in service!**

